



For:

- RTA Inspectors, Vehicle Regulations
- RTA Motor Registry Managers
- AIS/AUVIS Examiners
- AIS/AUVIS Proprietors
- Engineering Signatories

April 2000

www.rta.nsw.gov.au

Recall on Seat Belts fitted to Toyota Surf 4 door 130 series Vehicles

Introduction

The Roads and Traffic Authority (RTA) has been advised of a safety recall affecting Toyota Surf 4 door 130 series motor vehicles imported and certified under the Low Volume Compliance Plate Approval scheme.

The RTA has been advised that the rear outboard seat belts fitted to these vehicles might not comply with Australian Design Rule ADR 4/01 Seat Belts.

Although the manufacturer has attempted to contact the owners of these vehicles to arrange for any non-complying seat belts to be replaced, some owners may not have been contacted at this stage.

Action

When inspecting this type of vehicle, pay particular attention to the rear outboard seat belts. The manufacturer has undertaken to replace non-complying seat belts identified as PD.012 & PD.013 series belts.

If a vehicle is found to be fitted with these seat-belts, direct the owner to arrange for replacement by contacting the vehicle manufacturer (see the compliance plate for details), or contact:

Australian Transport Safety Bureau
Vehicle Recall Unit
PO Box 594
CANBERRA ACT
Tel. (02) 6274 7111 Fax. 02 6274 7477

FURTHER INFORMATION

RTA Blacktown:

Vehicle Regulation Unit
Level 1, 85 Flushcombe Road
PO Box 558
BLACKTOWN NSW 2148

Tel: (02) 9830 5555
Fax: (02) 9831 0913

RTA Wollongong:

Vehicle Regulation Unit
104 Market Street
PO Box 5398
WOLLONGONG NSW 2500

Tel: (02) 4226 7007
Fax: (02) 4225 8844

RTA Parkes:

Vehicle Regulation Unit
PO Box 334
PARKES NSW 2870

Tel: 1 800 809 388
Fax: (02) 6861 1496

RTA Newcastle:

Vehicle Regulation Unit
59 Darby Street
Locked Bag 30
NEWCASTLE NSW 2300

Tel: 1 800 049 920
or (02) 4924 0240
Fax: (02) 4323 9905